


City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Maheras Center



Inoperable drinking fountain.



Unclean restrooms and missing stall doors.

City of Detroit
Department of Recreation Performance Audit
Exhibit 1 – Maheras Center



Grass behind the center was 12 to 24 inches high.